



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JAN - 8 1996

Entergy Operations, Inc.
ATTN: J. W. Yelverton, Vice President
Operations, Arkansas Nuclear One
1448 S.R. 333
Russellville, Arkansas 72801-0967

SUBJECT: NRC INSPECTION REPORT 50-313/95-08; 50-368/95-08

Thank you for your letter of December 15, 1995, in response to our letter and Notice of Violation dated December 5, 1995. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

A handwritten signature in cursive script, appearing to read "J. E. Dyer".

J. E. Dyer, Director
Division of Reactor Projects

Clocks: 50-313
50-368
Licenses: DPR-51
NPF-6

cc:
Entergy Operations, Inc.
ATTN: Harry W. Keiser, Executive
Vice President & Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286-1995

Entergy Operations, Inc.
ATTN: Jerrold G. Dewease, Vice President
Operations Support
P.O. Box 31995
Jackson, Mississippi 39286

9601160416 960108
PDR ADOCK 05000313
G PDR

Entergy Operations, Inc.

-2-

Wise, Carter, Child & Caraway
ATTN: Robert B. McGehee, Esq.
P.O. Box 651
Jackson, Mississippi 39205

County Judge of Pope County
Pope County Courthouse
Russellville, Arkansas 72801

Winston & Strawn
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3502

Arkansas Department of Health
ATTN: Ms. Greta Dicus, Director
Division of Radiation Control and
Emergency Management
4815 West Markham Street
Little Rock, Arkansas 72201-3867

B&W Nuclear Technologies
ATTN: Robert B. Borsum
Licensing Representative
1700 Rockville Pike, Suite 525
Rockville, Maryland 20852

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01) *11/19*

bcc distrib. by RIV:

J. Callan
Branch Chief (DRP/C)
MIS System
RIV File
Project Engineer (DRP/C)

Resident Inspector
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRS-PSB
Branch Chief (DRP\TSS)

DOCUMENT NAME: R:\ ANO\AN508AK.KMK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:DRP/C	AC:DRP/C	D:DRP					
RLNease;df*	TReis*	JEDyer*					
1/5/96	1/5/96	1/8/96					

*previously concurred

OFFICIAL RECORD COPY

140089

E-Mail report to D. Nelson (DJN)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/C)
MIS System
RIV File
Project Engineer (DRP/C)

Resident Inspector
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)
DRS-PSB
Branch Chief (DRP\TSS)


DOCUMENT NAME: R:_ANO\AN508AK.KMK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:DRP/C	AC:DRP/C	D:DRP					
RLNease;df*	TReis*	JEDyer*					
1/5/96	1/5/96	1/8/96					

*previously concurred

OFFICIAL RECORD COPY




Entergy Operations, Inc.
1448 SR 333
Russellville, AR 72801
Tel: 871 858-5000

December 15, 1995

2CAN129505

U. S. Nuclear Regulatory Commission
Document Control Desk
Mail Station P1-137
Washington, DC 20555



Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Response To Notice Of Violation 50-368/9508-01

Reference: 2CAN119501 Dated November 2, 1995

Gentlemen:

Pursuant to the provisions of 10CFR2.201, the following is the subject response to the Notice of Violation identified during the inspection of activities associated with the Arkansas Nuclear One (ANO) Unit 2 Main Steam Safety Valve (MSSV) setpoints.

Entergy Operations agrees with this violation. The reason for the violation, corrective steps taken and corrective action to avoid further violations are documented in Licensee Event Report (LER) No. 50-368/95-005-00 dated November 2, 1995. Subsequent to identifying the unusually high setpoints of some of the MSSVs, corrective actions were implemented to properly test the MSSVs. Corrective actions have been implemented to prevent recurrence and are discussed in the LER. Full compliance with Unit 2 Technical Specifications was achieved prior to start-up following the recent refueling outage.

Should you have questions or comments, please call Mr. Dwight Mims at 501-858-4601

Very truly yours,

Dwight C. Mims
Director Nuclear Safety

DCM/RMC

96-0435

9512220065 zpp

U. S. NRC
December 15, 1995
2CAN129505 Page 2

cc: Mr. Leonard J. Callan
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

NRC Senior Resident Inspector
Arkansas Nuclear One
P.O. Box 310
London, AR 72847

Mr. George Kalman
NRR Project Manager Region IV/ANO-1 & 2
U. S. Nuclear Regulatory Commission
NRR Mail Stop 13-H-3
One White Flint North
11555 Rockville Pike
Rockville, MD 20852