

ENCLOSURE 1

NOTICE OF VIOLATION

Entergy Operations, Inc.  
River Bend Station

Docket: 50-458  
License: NPF-47

During an NRC inspection conducted from October 22 through December 2, 1995, two violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (60 FR 34381; June 30, 1995), the violations are listed below:

- A. 10 CFR Part 50, Appendix A, General Design Criterion 55 states, in part, that each line that is part of the reactor coolant pressure boundary and that penetrates primary reactor containment shall be provided with one automatic isolation valve inside and one locked closed isolation valve outside of containment unless it can be demonstrated that the containment isolation provisions for a specific class of lines are acceptable on some other design basis.

Contrary to the above, as of October 30, 1995, a primary containment penetration included a line that did not meet containment isolation provisions in that the low pressure core spray system instrument line did not contain one locked closed isolation valve outside of containment and no other demonstrated provisions were identified as acceptable.

This is a Severity Level IV violation (Supplement I) (458/9525-01).

- B. Technical Specification Surveillance Requirement 3.3.1.1.3 states, in part, that an adjustment of the average power range monitor channels be performed, every 7 days, to conform to a calibrated flow signal.

Contrary to the above, from August 26, 1994, to November 1, 1995, the licensee failed to perform Surveillance Requirement 3.3.1.1.3 in that the average power range monitor channels were not adjusted, to conform to a calibrated flow signal, every 7 days.

This is a Severity Level IV violation (Supplement I) (458/9525-03).

Pursuant to the provisions of 10 CFR 2.201, Entergy Operations, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved.

Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because the response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if it is necessary to include such information, it should clearly indicate the specific information that should not be placed in the PDR, and provide the legal basis to support the request for withholding the information from the public.

Dated at Arlington, Texas,  
this 9th day of *January* 1996