

## UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799-ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

#110 10 1884

Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. I. T. Yin of this office on June 8, 27-28, and July 27, 1984, of activities at Byron Station, Units 1 and 2, authorized by NRC Construction Permits No. CPPR-130 and No. CPPR-131, and to the discussion of our findings with Mr. E. D. Swartz of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Based on discussions during the July 27, 1984, meeting discussed in Paragraph 2.e of the enclosed report and our evaluation of the matter, we request that you provide this office (1) sufficient notification to allow us to observe selected snubber modification work in progress at Miller Fluid Power Company, and (2) the snubber re-qualification testing procedures for our review prior to conducting the tests.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure(s) will be placed in the NRC Public Document Room unless you notify this office, by telephone, within ten days of the date of this letter and submit written application to withhold information contained therein within thirty days of the date of this letter. Such application must be consistent with the requirements of 2.790(b)(1). If we do not hear from you in this regard within the specified periods noted above, a copy of this letter and the enclosed inspection report will be placed in the Public Document Room.

Commonwealth Edison Company 2 AUG 00 1934

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. L. Spessard, Director
Division of Reactor Safety

Enclosure: Inspection Report
No. 50-454/84-39(DRS);
No. 50-455/84-28(DRS)

cc w/encl: D. L. Farrar, Director of Nuclear Licensing V. I. Schlosser, Project Manager Gunner Sorensen, Site Project Superintendent R. E. Querio, Station Superintendent DMB/Document Control Desk (RIDS) Resident Inspector, RIII Byron Resident Inspector, RIII Braidwood Phyllis Dunton, Attorney General's Office, Environmental Control Division Ms. Jane M. Whicher Diane Chavez, DAARE/SAFE W. Paton, ELD L. Olshan, NRR LPM