


*Southern California Edison Company*



SAN ONOFRE NUCLEAR GENERATING STATION  
P.O. BOX 128  
SAN CLEMENTE, CALIFORNIA 92612

J. G. HAYNES  
STATION MANAGER

TELEPHONE  
(714) 492-7700

August 30, 1984

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: Docket No. 50-361  
Licensee Event Report No. 84-002, Revision 1  
San Onofre Nuclear Generating Station, Unit 2

Reference: (1) Letter, J. G. Haynes (SCE) to USNRC Document Control Desk,  
dated February 28, 1984, Licensee Event Report No. 84-002  
(2) Letter, J. G. Haynes (SCE) to USNRC Document Control Desk,  
dated June 21, 1984, Licensee Event Report No. 84-023

Reference (1) provided the required 30-day Licensee Event Report (LER) for occurrences involving the spurious actuation of the Containment Purge Isolation System (CPIS). We also reported that a revised LER, identifying the cause of the event and the corrective action taken, would be issued by August 31, 1984.

However, as a result of similar spurious actuations of the Control Room Isolation System (CRIS), reported in Reference (2), we have expanded our investigation into noise spikes to include both CPIS and CRIS monitors. We have retained a contractor, specializing in noise reduction, who is evaluating monitor performance data. This investigation will not be completed until December 31, 1984, at which time revisions to LER 84-002 and 84-024 will be submitted.

If you require any additional information, please so advise.

Sincerely,

cc: A. E. Chaffee (USNRC Resident Inspector, Units 1, 2 and 3)  
J. P. Stewart (USNRC Resident Inspector, Units 2 and 3)  
J. B. Martin (Regional Administrator, USNRC Region V)

8409070351 840830  
PDR ADOCK 05000361  
S PDR

IE22  
1/0