

Arizona Public Service Company

August 23, 1984
ANPP-30317-TDS/TRB

U. S. Nuclear Regulatory Commission
Region V
Creekside Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director
Division of Resident
Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-27
A 50.55(e) Potentially Reportable Deficiency Relating To
Improperly Handled Instrumentation From Waldinger.
File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on
May 10, 1984
(B) ANPP-29648, dated June 4, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available by
August 24, 1984.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by September 28, 1984,
at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E. E. Van Brunt, Jr.
E. E. Van Brunt, Jr.
APS Vice President
Nuclear Production
ANPP Project Director

REGION V AS

EEVB/TRB/nj

cc: See Page Two

8407070393 840823
PDR ADDCK 05000528
PDR
S

RECEIVED
NRC

1984 AUG 27 AM 11:46

110
IE-27

Mr. T. W. Bishop
DER 84-27
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
J. Vorees
J. R. Bynum
J. M. Allen
J. A. Brand
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
L. E. Vorderbrueggen
R. P. Zimmerman
S. R. Frost
J. Self
M. Woods
T. J. Bloom
D. Canady

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339