

CP&L

PRP
OFFICIAL COPY

Carolina Power & Light Company

84 AUG 27 P 1: 44

P. O. Box 101, New Hill, NC 27562
August 21, 1984

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 2900)
Atlanta, GA 30323

NRC-258

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1986 - 900,000 KW - UNIT 1
PIPE FRAME - MATERIAL OMISSION, ITEM 182


Dear Mr. O'Reilly:

On July 27, 1984, Mr. N. J. Chiangi notified the NRC (Mr. A. Hardin) of a potentially reportable item per the provisions of 10CFR50.55(e). The NRC was informed that contrary to the requirements of AISC Section 5, washers were not placed on both sides of plied connections for pipe frame C-1-364 when oversized or short slotted holes existed.

An investigation is currently underway to identify other connections which may be suspect. Once our investigation is complete, an engineering evaluation will be performed to determine acceptability. It is projected that a report on the reportability of this item will be issued by October 23, 1984.

Thank you for your consideration in this matter.

Yours very truly,



R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/jam

cc: Messrs. G. Maxwell/R. Prevatte (NRC - SHNPP)
Mr. R. C. DeYoung (NRC)

8409100024 840821
PDR ADOCK 05000400
S PDR

OFFICIAL COPY

1/0 IE 27