Carolina Power & Light Company Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429 August 28, 1984 FILE: B09-13510C

SERIAL: BSEP/84-1862

NRC Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

> BRUNSWICK STEAM ELECTRIC PLANT UNIT 1 DOCKET NO. 50-325 LICENSE NO. DPR-71 LICENSEE EVENT REPORT 1-84-15

Gentlemen:

On August 6, 1984, it was determined that a technical specification required surveillance procedure, associated with the radioactive gaseous effluent monitors of the Reactor Building on both units, may not be adequate to fully meet the requirements of footnotes listed in technical specifications. Subsequent technical reviews of other similar procedures have revealed possible additional findings. The Licensee Event Report of these discoveries, identified as LER 1-84-15, was to be submitted to your office by September 5, 1984; however, the investigation and evaluation concerning this event is not yet complete. LER 1-84-15 will be submitted by October 5, 1984.

Very truly yours,

01-5

C. R. Dietz, General Manager Brunswick Steam Electric Plant

MJP/jlh/LETJH1

cc: Mr. R. C. DeYoung Mr. J. P. O'Reilly

8409100043 840828 PDR ADOCK 0500032