



#1612

May 11, 1992

Mr. Thomas Murley
Director - Office of Nuclear Reactor Regulation
11555 Rockville Pike
Rockville, Maryland 20852

Subject: 10CFR21 Reporting of Defects and Non-Compliance -
MKW Power Systems Report No. 10CFR21-0062

Reference: Diesel Generators with EMC 645 Series Engines using
turbochargers that were remanufactured from May,
1991 to January, 1992

Dear Mr. Murley:

Enclosed is a copy of the above report which concerns a potential
defect with the engine turbocharger planetary bearing shaft.

A copy of this report has been mailed to customers affected by this
notification.

Should you have questions, please feel free to call.

Yours very truly,

MKW POWER SYSTEMS, INC.

M. Vann Mitchell

M. Vann Mitchell
Quality Manager

MVM:jb

Enclosure

200083

Ltr. Encl.

ADD: Andy Kugler
Nancy Campbell

JEL 9

Post Office Box 1928 • Rocky Mount, North Carolina 27802-1928 • Phone: (919) 977-2720
TWX: (510) 929-0725 • FAX: (919) 446-3830

9205210231 920511
JR ADOCK 05000263
S PDR

Rec'd
JUL 5