

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-483/84-33(DRSS)

Docket No. 50-483

License No. NPR-25

Licensee: Union Electric Company
Post Office Box 149 - Mail Code 400
St. Louis, MO 63166

Facility Name: Callaway County Nuclear Power Station, Unit 1

Inspection At: Callaway County, MO

Inspection Conducted: July 5-6, 11-12 and August 13-16, 1984 (onsite)
July 9-10, 17-20, 31 and August 8 and 20, 1984
(Region III Office)

Type of Inspection: Announced Special Physical Security Inspection

Date of Previous Physical Security Inspection: May 14-18 and 29-30, 1984

Inspector: *J. L. Pirtle* 9/5/84
G. L. Pirtle Date
Physical Security Inspector

Approved By: *J. R. Creed* 9/5/84
J. R. Creed, Chief Date
Physical Security Section

Inspection Summary

Inspection on July 5-August 20, 1984 (Report No. 50-483/84-33[DRSS])
Areas Inspected: Included a review of the licensee's actions for security-related Licensee Event Reports (LERs) received by NRC Region III between June 11 and August 13, 1984. The licensee's progress in reducing nuclear security force personnel overtime was also reviewed. The inspection involved 48 inspector man-hours onsite by one NRC inspector. Four of the 48 man-hours were conducted during off-shift periods. Thirteen inspector man hours were conducted at the Regional Office.
Results: Based on this inspection, two violations were identified.

- a. Protection of Safeguards Information: Some Licensee Event Reports which contained Safeguards Information were not properly marked and controlled (paragraph 3.a.).

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

- b. Compensatory Measures: Required compensatory measures were not implemented (paragraph 3.b.).

The licensee's investigative actions and temporary increased security measures pertaining to a security related incident which occurred on July 4, 1984, were considered adequate and commitments made in the July 16, 1984 Confirmation of Action Letter were adequately implemented. Corrective actions pertaining to security-related LERs were generally adequate. Progress in reducing unplanned computer outages was considered adequate. Reduction of security force overtime was also considered as progressing adequately.

(Details - UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled