



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 19 1992

Docket No. 50-440
License No. NPF-58

Centerior Service Company
ATTN: Mr. Michael D. Lyster
Vice President
Nuclear - Perry
c/o The Cleveland Electric Illuminating
Company
10 Center Road
Perry, OH 44081

Dear Mr. Lyster:

This confirms our plans as discussed between Mr. H. Miller, Director, Division of Reactor Safety, and yourself to conduct a management meeting at 10:00 a.m. (CDT) on Wednesday, May 27, 1992, at the Region III office in Glen Ellyn, IL. The purpose of the meeting is to discuss the current status of the Main Steam Isolation Valves (MSIVs) that failed leak rate testing, root cause(s) of the failures, and corrective actions.

We will gladly discuss any questions you may have regarding this matter.

Sincerely,

Edward G. Greenman, Director
Division of Reactor Projects

See Attached Distribution:

9205270193 920519
PDR ADOCK 05000440
P PDR

00006

JEAS
1/0

Distribution:

cc:

F. R. Stead, Director, Nuclear
Support Department

R. A. Stratman, General Manager,
Perry Nuclear Power Plants

Kevin P. Donovan, Manager,
Licensing and Compliance Section

S. F. Kensicki, Director, Perry
Nuclear Engineering Dept.

H. Ray Caldwell, General
Superintendent Nuclear Operations

DCD/DCB(RIDS)

Licensing Fee & Debt Collection Branch

Resident Inspector, RIII

Terry J. Lodge, Esq.

James R. Williams, State of Ohio

Robert E. Owen, Ohio

Department of Health

A. Grandjean, State of Ohio,

Public Utilities commission

Clinton SRI