

1764

RELATED CORRESPONDENCE

KIRKPATRICK, LOCKHART, HILL, CHRISTOPHER & PHILLIPS

A PARTNERSHIP INCLUDING A PROFESSIONAL CORPORATION

1900 M STREET, N. W.

WASHINGTON, D. C. 20036

TELEPHONE: (202) 452-7000

TELEX: 440209 HIPH UI

1486 BRICKELL AVENUE
MIAMI, FLORIDA 33131
(305) 374-0112

1500 OLIVER BUILDING
PITTSBURGH, PENNSYLVANIA 15222
(412) 355-6500

SEP 11 10:13

OFFICE OF SECRETARY
DOCKETING & SERVICE
BRANCH

WRITER'S DIRECT DIAL NUMBER

(202) 452-6774

September 7, 1984

Lawrence J. Brenner, Esq.
Dr. Peter A. Morris
Administrative Judges
Atomic Safety and Licensing Board
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dr. George A. Ferguson
Administrative Judge
Howard University
School of Engineering
2300 - 6th Street, N.W.
Washington, D.C. 20059

Re: Long Island Lighting Company; Shoreham Nuclear Power Station,
Unit 1; Docket No. 50-322-OL

Gentlemen:

Suffolk County hereby provides the following list of errata for its July 31 Joint Direct Testimony:

1. Page 6, first answer, tenth and eleventh lines -- the phrase beginning with "an engineering . . ." should read "as an estimator and contracts engineer responsible for producing ships' specifications for newbuildings to potential owners' requirements."
2. Page 12, second answer, second line -- the phrase reading "having a 17" stroke and a 21" bore" should read "having a 21" stroke and a 17" bore."
3. Page 17, ninth line -- the number "34" should read "24."
4. Page 37, second line -- the word "Vender" should read "Vendor."
5. Page 49, first question, first line -- the word "affect" should read "effect."

8409110406 840907
PDR ADOCK 05000322
G PDR

add your
JOCA

DS03

Lawrence J. Brenner, Esq.
Dr. Peter A. Morris
Dr. George A. Ferguson
September 7, 1984
Page Two

6. Page 50, second line -- the word "inbalances" should read "imbalances."
7. Page 52, footnote 63, second line -- a semicolon should follow Q-83, not a colon.
8. Page 58, fifth line -- the words "blow by" should read "blow-by."
9. Page 60, subsection (b), second line -- the word "precedure" should read "procedure."
10. Page 63, last paragraph, second line -- the word "Owners" should read "Owners'."
11. Page 69, last line -- the word "cast" should read "casting."
12. Page 74, eighth line -- the word "analyses" should read "analysis."
13. Page 91, twelfth line -- the word "sampliyng" should read "sampling."
14. Page 95, first full answer, seventh line -- the word "raisers" should read "risers."
15. Page 98, fourth line -- the word "head" should be deleted.
16. Page 106, first answer, sixth line -- the word "stardards" should read "standards."
17. Page 108, first full answer, twelfth line -- the word "Owners" should read "Owners'."
18. Page 111, second answer, second line -- the word "foreward" should read "foreword."
19. Page 139, fourth line -- the word "raisers" should read "risers."
20. Page 139, ninth line -- the word "raisers" should read "risers."
21. Page 144, eighth line -- the word "be" should be deleted.

Lawrence J. Brenner, Esq.
Dr. Peter A. Morris
Dr. George A. Ferguson
September 7, 1984
Page Three

22. Page 148, sixth line -- the word "Owners" should read "Owners'."

23. Page 149, first line -- the word "Owners" should read "Owners'."

24. Page 149, first question, first line -- the word "Owners" should read "Owners'."

25. Page 149, first answer, third line -- the word "Owners" should read "Owners'."

26. Page 150, first answer, second line -- the word "Owners" should read "Owners'."

27. Page 150, second question, first line -- the word "Owner's" should read "Owners'."

28. Page 151, eleventh line -- the words "so called" should read "so-called."

29. Page 156, fourteenth line -- the word "engines" should follow the word "non-nuclear."

30. Page 163, eleventh line -- the word "inch" should follow the number "2½."

31. Page 164, sixteenth line -- the word "is" should read "in."

32. Page 173, eleventh line -- the word "EDG's" should read "EDGs."

33. Page 181, first line -- the word "intitiation" should read "initiation."


In addition, the County hereby corrects its testimony concerning the peak firing pressures in the EDGs at full load (3500kW). Beginning on page 30 of the County's Joint Direct Testimony, the County's witnesses refer in a number of instances to reported peak firing pressures of 1750 psi at full load. That testimony, however, was based on a mistaken reading of the TDI EDG test bed data appearing in the County's Exhibit 46, Document 6. The appropriate reported maximum figure for peak firing pressure in the

KIRKPATRICK, LOCKHART, HILL, CHRISTOPHER & PHILLIPS

Lawrence J. Brenner, Esq.
Dr. Peter A. Morris
Dr. George A. Ferguson
September 7, 1984
Page Four

EDGs at full load is 1720 psi, as indicated in the County's
Exhibit 46, Document 7.

Very truly yours,

A handwritten signature in cursive script that reads "Douglas J. Scheidt". The signature is written in dark ink and is positioned above the typed name.

Douglas J. Scheidt

DJS/ss
cc: Service List