

DeB/DeB(Rios)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 22 1992

Docket No. 50-266
Docket No. 50-301

Wisconsin Electric Power Company
ATTN: Mr. Robert Link
Vice President
Nuclear Power
231 West Michigan Street - P379
Milwaukee, WI 53201

Dear Mr. Link:

This refers to the NRC's Systematic Assessment of Licensee Performance (SALP) 9 Report for the Point Beach Nuclear Plant, our meeting of April 30, 1992, which discussed in detail the contents of the report, and your written comments dated May 13, 1992, relative to the report.

Based on our discussions during the meeting and our review and evaluation of your letter of response, we have reached the conclusion presented in the enclosed meeting summary. With the incorporation of the revised page from Enclosure 3, the Initial SALP Report dated April 20, 1992, should be considered to be the Final SALP Report.

At the request of your staff, copies of the NRC presentation material were distributed at the SALP meeting. A copy of this material is included as Enclosure 4 to this letter.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter with the referenced enclosures, will be placed in the NRC's Public Document Room.

No reply to this letter is required; however, should you have questions regarding the Final SALP Report, please let us know and we will be pleased to discuss them with you.

Sincerely,

Carl J. Paparella
A. Bert Davis
Regional Administrator

- Enclosures:
1. Final SALP 9 Reports
No. 50-266/92001; 50-301/92001
(Meeting Summary)

See Attached Distribution

9206020210 920522
PDR CHECK 05000266
G PDR

IEAO
|||

MAY 22 1992

2. Revision sheet
3. Revised Page to SALP Report
4. SALP meeting presentation material
5. Licensee Response Ltr,
dtd May 13, 1992

Distribution

cc w/enclosure:

G. J. Maxfield, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII
Virgil Kanable, Chief
Boiler Section
Charles Thompson, Chairman
Wisconsin Public Service
Commission
Robert M. Thompson, Administrator
WI Div of Emergency Govt.
INPO

The Chairman

K. C. Rogers, Commissioner
J. R. Curtiss, Commissioner
F. J. Remick, Commissioner
L. G. de Planque, Commissioner
J. H. Sniezek, DEDR
T. E. Murley, Director, NRR
State Liaison Officer, State
of Wisconsin
Chief, LPEB, NRR (2 copies)
J. N. Hannon, NRR Director, Project Director - 19 III-3
J. Lieberman, Director, Office of Enforcement
R. DeFayette, RIII
K. Jury, SRI
L. L. Cox, RIII (2 copies)
TSS, RIII
RIII Files
RIII PRR

Point Beach Nuclear Plant

A. Summary of Meeting with Wisconsin Electric Power Company on April 30, 1992

The findings and conclusions of the SALP Board are documented in Reports No. 50-266/92001; 50-301/92001 and were discussed with the licensee on April 30, 1992, at Two Rivers, Wisconsin.

While the meeting was primarily a discussion between the licensee and NRC, it was open to members of the public as observers.

The following licensee and NRC personnel were in attendance, as well as the noted observers.

Wisconsin Electric Power Company

R. Abdo	Chairman and Chief Executive Officer
J. Boston	President and Chief Operating Officer
J. Zach	Vice President, Nuclear Power
R. Link	Vice President, Marketing
G. Maxfield	Manager, Point Beach Nuclear Plant
G. Krieser	Manager, Quality Assurance
G. Frieling	Manager, Nuclear Engineering
E. Lipke	Manager, Nuclear Technical Services
C. Meyer	Manager, Corporate Security

Nuclear Regulatory Commission

A. Davis	Regional Administrator
E. Greenman	Director, Division of Reactor Projects (DRP)
J. Hannon	Director, Project Directorate III-3
R. Knop	Chief, Branch 3, DRP
I. Jackiw	Chief, Section 3A, DRP
A. Hansen	Project Manager
K. Jury	Senior Resident Inspector
J. Gadzala	Resident Inspector
K. O'Brien	Resident Inspector, Kewaunee

Other

D. Hernet	Reporter, Herald Times
-----------	------------------------

B. Comments Received from Licensee

Wisconsin Electric Power Company's response to the Point Beach Initial SALP 9 Report dated May 13, 1992, included comments that have resulted in a minor revision to the Initial SALP Report. This change is listed in Enclosure 2 and the revised page is included as Enclosure 3.

The affected page of the Initial SALP Report should be replaced with the corrected page included in Enclosure 3.

C. Regional Administrator's Conclusions Based on Consideration of Licensee Comments

I have concluded that the overall ratings in the affected areas have not changed.