



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

JUN 1 1992

Docket No. 50-382
License No. NPF-38


Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box 8
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05

Thank you for your letter of May 15, 1992, in response to our letter and Notice of Violation dated April 8, 1992. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We note that your response to Violation 9205-01 stated that your final corrective action is contingent upon the outcome of a Region IV backfit panel considering similar issues involving test methodology at another Entergy site. We find your approach acceptable. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,


A. Bill Beach, Director
Division of Reactor Projects

cc:
Entergy Operations, Inc.
ATTN: Donald C. Hintz, President
& Chief Operating Officer
P.O. Box 31995
Jackson, Mississippi 39286

9206050361 920601
PDR ADDCK 05000382
Q PDR

TECH 11