

Southern Nuclear Operating Company
Post Office Box 1295
Birmingham, Alabama 35201
Telephone (205) 868-5131



Southern Nuclear Operating Company
the southern electric system

Dave Morey
Vice President
Farley Project

February 2, 1996

Docket No.: 50-348

U. S. Nuclear Regulatory Commission
ATTN.: Document Control Desk
Washington, D. C. 20555

Joseph M. Farley Nuclear Plant - Unit 1
Steam Generator Tube Interim Repair Criteria Data Report

Ladies and Gentlemen:

In order to receive a voltage-based interim repair criteria for outside diameter stress corrosion cracking at tube support plate intersections, Southern Nuclear Operating Company committed to submit the information required by Generic Letter 95-05, "Voltage-Based Repair Criteria For Westinghouse Steam Generator Tubes Affected By Outside Diameter Stress Corrosion Cracking."

The required information is provided in the attached report.

If there are any questions, please advise.

Respectfully submitted,

Dave Morey

REM/maf: ipcrprt.doc

Attachment

cc: Mr. S. D. Ebnetter
Mr. B. L. Siegel
Mr. T. M. Ross
Mr. T. A. Reed

080070

9602080201 960202
PDR ADOCK 05000348
P PDR

Pool
1/1