




LOUISIANA

POWER & LIGHT / Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 30, 1984

W3K84-2036
Q-3-A35.07.90

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-1905 dated August 16, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 90
"Electrical Conduit Overstressed"
Fifth Interim Report

The above referenced letter indicated submittal of an Interim and/or Final Report to the USNRC on August 30, 1984.

At the present time, additional walkdowns are being conducted to verify corrective action and is scheduled to be completed in mid September 1984. The Final Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

EE-27

1/0

Mr. John T. Collins
August 30, 1984
W3K84-2036
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814