


**LOUISIANA**

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 30, 1984

W3K84-2035  
Q-3-A35.07.105

Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012



REFERENCE: LP&L letter W3K84-1904 dated August 17, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 105  
"Electrical Separation Deficiencies (Regulatory Guide 1.75)"  
Fourth Interim Report

The above referenced letter indicated submittal of an Interim and/or Final Report to the USNRC on August 31, 1984.

At the present time, corrective actions discovered in the walk down effort are scheduled to be completed in mid September 1984. An Interim and/or Final Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8409170185 840830  
PDR ADOCK 05000382  
S PDR

IE-27  
/0

Mr. John T. Collins

August 30, 1984

W3K84-2035

Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814