Arizona Public Service Company

August 29, 1984 ANPP-30350-TDS/TRB

U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368

Attention: Mr. T. W. Bishop, Director Division of Resident Reactor Projects and Engineering Programs

Subject: Time Extension For Report - DER 84-37 A 50.55(e) Potentially Reportable Deficiency Relating To Unauthorized/Unqualified Duct Sealant. File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on May 17, 1984 (B) ANPP-19714, dated June 12, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by August 30, 1984.

Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by September 20, 1984, at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this time.

Very truly yours,

E.E. Van Brunt age

E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director


USI A HOIDER

SH :1 Hd 7- d3S 1861

HECEIAED

EEVB/TRB/nj

cc: See Page Two



Mr. T. W. Bishop DER 84-37 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr. D. B. Karner W. E. Ide D. B. Fasnacht A. C. Rogers L. A. Souza D. E. Fowler T. D. Shriver C. N. Russo J. Vorees J. R. Bynum J. M. Allen J. A. Brand D. Canady A. C. Gehr W. J. Stubblefield W. G. Bingham R. L. Patterson R. W. Welcher H. D. Foster D. R. Hawkinson L. E. Vorderbrueggen R. P. Zimmerman S. R. Frost L. Clyde M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339