

APPENDIX A

NOTICE OF VIOLATION

Public Service Electric and  
Gas Company  
Salem Units 1 and 2

Docket/License: 50-272/DPR-70  
Docket/License: 50-311/DPR-75

As a result of the review of your submittal, dated July 13, 1984, in response to our letter, dated June 12, 1984, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

- A. The May 6, 1983 Order Modifying the License Effective Immediately required that the licensee implement and/or maintain the items specified in the licensee's letter dated April 28, 1983.

The licensee's April 28, 1983 letter stated that the following corrective actions were complete:

1. Instruct appropriate personnel in purpose and use of MEL (C.1.a.2); and,
2. Conduct a training program to ensure that work orders are properly classified (C.3.a.2).

Contrary to the above, personnel involved with classifying Work Orders MD946229 and MD946237 were not properly trained in the classification logic detailed in memorandum, CD-M-60 which is an addendum to the MEL, in that the work orders were not properly classified as safety related.

This is a Severity Level IV violation (Supplement 1) applicable to both DPR-70 and DPR-75.

Pursuant to the provisions of 10 CFR 2.201, Public Service Electric and Gas Company is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

OFFICIAL RECORD COPY

RL50-272/84-15 - 0003.0.0  
08/07/84

8409170286 840822  
PDR ADOCK 05000272  
Q PDR