

MAN OFFICE MANAGER MANAGER MT. ARLINGTON, N.J. 07856 (201) 398-8163 • FAX: (201) 398-8037

May 1, 1991

220-29189

PØ3

Dr. Mohamed Shambaky, Chief Nuclear Materials Safety Section A Division of Radiation 5 'ety and Safeguards U.S. NUCLEAR REGULATORY OMMISSION -- REGION I 475 Allendale Road King Of Prussia, Pennsylvania 19496

Re: RENEWAL AND AMENDMENT OF MATERIALS LICENSE NO. 29-27823-01

Dear Dr. Shambaky:

We request that the license referenced above be renewed and amended as follows. The amendment/renewal application is provided as attachment 1.

The address specified in license item 2 should be changed to the address of our headquarters office: 111 Howard Boulevard, Mt. Arlington, New Jersey 07856. The materials listed in the license will be stored and used at this location.

The contact person for the purposes of this license should be changed from Dr. Zvi Blank to Mr. Mark London. Dr. Blank is no longer associated with Enviro-Sciences.

The information in items 6 through 10 should be amended to show that the Hydrogen 3 source has been returned to the equipment manufacturer. The Certification of Disposition of Materials form has been sent to the NRC in a separate letter. A copy is attached for your information (attachment 2).

In addition, items 6 through 10 should be amended to show that we possess two (2) additional calibration pources: Im

-Radium 226; sealed source; 100 microcuries

In our letter of February 13, 1989, we reduce the addition of the radium sealed source to our license (Ettachment 3). The cesium source was inadvertently not listed in our letter. It was provided as a calibration source with a radon detection meter. The two sources noted above and the 10-microcurie cesium source currently listed on the license will all be stored and used at the 111 Howard Boulevard location.

9206100088 920518 NMSS LIC30 29-27823-01 PDR License Fee Information on application

1001

Item 11 should be modified to remove the names of Zvi Blank, James Licata, and Theodore Russen. They are no longer members of our staff. The following names should be added to item 11: Mark London, MS and Susanne Storms, BS.

Items 12 and 14 should be deleted. They refer to the Hydrogen 3 source in the detector cell that has been returned to the

If you have any questions, I can be contacted at the phone number above. Thank you for your cooperation in this matter.

Sincerely,

ENVIRO-SCIENCES, INC.

Mail London

Mark London, Assistant Vice President

cc: Irving Cohen Zvi Blank



10

P04