VIRGINIA ELECTRIC AND POWER COMPANY Richmond, Virginia 28261

June 1, 1992

U. S. Nuclear Regulatory Commission Attn.: Document Control Desk Washington, D.C. 20555 Serial No. 92-366 NES/ISI/PJN/TAH: R0 Docket Nos.: 50-338 License Nos.: NPF-4

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY NORTH ANNA POWER STATION UNIT 1 1992 STEAM GENERATOR INSPECTION OUTAGE INSERVICE INSPECTION SUMMARY REPORT

Pursuant to the provisions of ASME Section XI, Virginia Electric and Power Company hereby submits the enclosed Inservice Inspection Report for the North Anna Power Station Unit 1 1992 steam generator inspection outage. This report is a summary of examinations performed during the outage to conclude the first period of the North Anna Unit 1 second ten-year inservice inspection interval. The report consist of three attachments.

The first attachment, Form NIS-1, Owner's Report for Inservice Inspections, and the second attachment, Forms NIS-2, Owner's Report of Repair and Replacement and the associated summaries, are provided pursuant to IWA-6220 of the 1983 Edition of ASME Section XI, Summer 1983 Addenda. The third attachment provides the Evaluation Analysis of Examination Results pursuant to IWB-3125(b) of the 1983 Edition of ASME Section XI, Summer 1983 Addenda.

If you have any further questions, please contact us.

Very truly yours,

Danlon

fov W. L. Stewart Senior Vice President - Nuclear

Attachments

050075

Docket Nos.: 50-338 Serial No. 92-360 Page 2 of 2

pc: U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, N.W. Suite 2900 Atlanta, Georgia 30323

.

. 4

Mr. M. S. Lesser NRC Senior Resident Inspector North Anna Power Station