



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Date 9-13-84

REF: Facility Byron
Inspection Report No(s). 50-454/84-44

OR License No(s). _____

Thank you for your letter dated September 10, 1984,
informing us of the steps you have taken to correct the non-
compliance which we brought to your attention in our letter
dated July 30, 1984. We will examine these matters during
a future inspection.

Sincerely,

R. L. Spessard, Director
Division of Reactor Safety

8409180352 840913
PDR ADDCK 05000454
Q PDR

RII *WK*
Kropp/lid
09/13/84

RII *H*
Hawkins

RII *R. D. Walker*
Walker

RII *G. L. Hayes*
Hayes

RII *R. L. Spessard*
Spessard

11
1501