Drywell 3.6.5.1

SURVEILLANCE REQUIREMENTS (continued)

SURVEILLANCE		FREQUENCY NOTE SR 3.0.2 is not applicable for extensions > 12 months. 24 months following 2 consecutive tests with bypass leakage greater than the bypass leakage limit until 2 consecutive tests are less than or equal to the bypass leakage limit AND
SR 3.6.5.1.3 Verify bypass leakage is less than or equal to the bypass leakage limit. However, during the first unit startup following bypass leakage testing performed in accordance with this SR, the acceptance criterion is ≤ 10% of the drywell bypass leakage limit.		
		48 months following a test with bypass leakage greater than the bypass leakage limit AND
		120 months