

Duke Power Company  
P.O. Box 1007  
Charlotte, N.C. 28201-1007

Hal B. Tucker  
Senior Vice President  
Nuclear  
(704) 373-4531



DUKE POWER

June 11, 1992

U. S. Nuclear Regulatory Commission  
ATT: Document Control Desk  
Washington, DC 10555

Subject: McGuire Nuclear Station, Unit 2  
Docket No. 50-370  
Inservice Inspection  
1991 Refueling Outage 7

Attached is controlled copy No.5 of the Inservice Inspection Report which summarizes inservice inspection results for the subject refueling outage. This report is being submitted in accordance with the ASME Code Section XI.

Any questions may be directed to Andrew J. Hogge at (704) 373-8907.

Very truly yours,

A handwritten signature in cursive script, appearing to read "Hal B. Tucker".

H. B. Tucker

LTB/

XC: W/O Attachment

S. D. Ebnetter  
Regional Administrator, Region II

P. K. VanDoorn  
Senior Resident Inspector

T. A. Reed, ONRR

9206160221 920611  
PDR ADOCK 05000370  
G PDR

AOA7  
1/1