

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE

Diagnostic Health Services
4 N 370 84TH COURT
Bartlett, IL 60103

2. REGIONAL OFFICE

REGION III
U S NUCLEAR REGULATORY COMMISSION
801 WARRENVILLE ROAD
LISLE IL 60532-4351

3. DOCKET NUMBER(S)

030-14235

4. LICENSE NUMBER(S)

12-13568-02

5. DATE OF INSPECTION

11/2 - 12/5/95

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☐ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.

☒ A. The Hot lab in Warsaw, IN was not properly posted to indicate the presence of a licensed material, on 11/2/95. 10 CFR 20.1904(e) or 34.42.

☐ B. 1 kg of of sealed sources were not performed at the proper frequencies. 10 CFR or License Condition Number .

☐ C. Records of were not properly maintained. 10 CFR or License Condition Number .

☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.

☐ E. Reports or notification of were not made in accordance with 10 CFR or License Condition Number .

☒ F. On 8/1/95, the licensee (MICA) transferred ownership to Diagnostic Health Services and did not allow NRC to find that the transfer was in accordance with the Act and give written consent as required by 10 CFR 30.143-30.344-1

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE

DATE

SIGNATURE - NRC INSPECTOR

DATE

Arwin P. D.

1-8-96

Thomas Young

12/19/95

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE Diagnostic Health Services 4 N 370 84th Court Bartlett, IL 60103		2. REGIONAL OFFICE REGION III U S NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S) 030-14235	4. LICENSE NUMBER(S) 12-13568-02	5. DATE OF INSPECTION 11/2 - 12/5/95	

3. (Continued)

☒ G.

On 11/2/95, the technologist in Warsaw, IN did not wear personnel monitoring devices while in the hot lab when licensed material was handled and the Mo-99/Tc-99m generator was eluted, as required by License Condition 14.A, application dated March 31, 1992, Item 10.4, "Safe Use of Radioactive Material".

☐ H.☐ I.

4.

The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☐ A.☐ B.☐ C.