

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

September 14, 1984

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Denton:

ULNRC- 926

DOCKET NUMBER 50-483
CALLAWAY PLANT, UNIT 1
LICENSE CONDITION 2.C.7.a - FIRE PROTECTION

Reference: ULNRC-814 dated May 7, 1984

The following information is provided relative to closing License Condition 2.C.7.a of the Callaway Operating License, NPF-25. This License Condition, relating to fire protection, resulted from a deferral requested by the referenced letter.

1. The South Penetration Room Halon system is considered complete and operational as a result of the testing and the addition of a sprinkler system for the electrical chase area. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. The SNUPPS Standard Plant FSAR was revised in Revision 15 to describe the added sprinkler system.
2. The line-type thermal detectors (Protecto-Wire) inside containment have been successfully tested and declared operable. Union Electric has determined that the thermal detectors for the cable trays on the control rod drive mechanism are not required and, therefore, has deleted them from the design. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. This change does not necessitate an FSAR change.
3. The construction activities related to the Auxiliary and Control Building passive fire protection items described in the referenced letter were completed on August 24, 1984. As a result of modification implementation and closure of quality control paperwork, a small number of inoperable penetrations continue to exist. To ensure compliance with Technical Specifications and the Fire Protection Program until these are resolved, required fire watches are being maintained as compensatory measures.


8409200213 840914
PDR ADOCK 05000483
F PDR

A006
1/1

Mr. Harold R. Denton
September 14, 1984
Page 2

We believe this submittal closes License Condition 2.C.7.a
of the Callaway Operating License.

Very truly yours,



for Donald F. Schnell

DS/msc


cc: J. Holonich

STATE OF MISSOURI)
) S S
CITY OF ST. LOUIS)

Robert J. Schukai, of lawful age, being first duly sworn upon oath says that he is General Manager-Engineering (Nuclear) for Union Electric Company; that he has read the foregoing document and knows the content thereof; that he has executed the same for and on behalf of said company with full power and authority to do so; and that the facts therein stated are true and correct to the best of his knowledge, information and belief.

By 
Robert J. Schukai
General Manager-Engineering
Nuclear

SUBSCRIBED and sworn to before me this *14th* day of *September*, 198*4*


MARY C. GUINN
NOTARY PUBLIC—STATE OF MISSOURI
ST. LOUIS CITY
MY COMMISSION EXPIRES JUNE 16, 1985

cc: Gerald Charnoff, Esq.
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Nicholas A. Petrick
Executive Director
SNUPPS
5 Choke Cherry Road
Rockville, Maryland 20850

John H. Neisler
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

William Forney
Division of Projects and
Resident Programs, Chief, Section 1A
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Bruce Little
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

September 14, 1984

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Denton:

ULNRC-926

DOCKET NUMBER 50-483
CALLAWAY PLANT, UNIT 1
LICENSE CONDITION 2.C.7.a - FIRE PROTECTION

Reference: ULNRC-814 dated May 7, 1984


The following information is provided relative to closing License Condition 2.C.7.a of the Callaway Operating License, NPF-25. This License Condition, relating to fire protection, resulted from a deferral requested by the referenced letter.

1. The South Penetration Room Halon system is considered complete and operational as a result of the testing and the addition of a sprinkler system for the electrical chase area. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. The SNUPPS Standard Plant FSAR was revised in Revision 15 to describe the added sprinkler system.
2. The line-type thermal detectors (Protecto-Wire) inside containment have been successfully tested and declared operable. Union Electric has determined that the thermal detectors for the cable trays on the control rod drive mechanism are not required and, therefore, has deleted them from the design. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. This change does not necessitate an FSAR change.
3. The construction activities related to the Auxiliary and Control Building passive fire protection items described in the referenced letter were completed on August 24, 1984. As a result of modification implementation and closure of quality control paperwork, a small number of inoperable penetrations continue to exist. To ensure compliance with Technical Specifications and the Fire Protection Program until these are resolved, required fire watches are being maintained as compensatory measures.

Mr. Harold R. Denton
September 14, 1984
Page 2

We believe this submittal closes License Condition 2.C.7.a
of the Callaway Operating License.

Very truly yours,


for Donald F. Schnell

DS/msc

cc: J. Holonich

cc: Gerald Charnoff, Esq.
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Nicholas A. Petrick
Executive Director
SNUPPS
5 Choke Cherry Road
Rockville, Maryland 20850

John H. Neisler
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

William Forney
Division of Projects and
Resident Programs, Chief, Section 1A
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Bruce Little
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

UNION ELECTRIC COMPANY

1901 GRATIOT STREET
ST. LOUIS, MISSOURI

DONALD F. SCHNELL
VICE PRESIDENT

September 14, 1984

MAILING ADDRESS:
P. O. BOX 149
ST. LOUIS, MISSOURI 63166

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr. Denton:

ULNRC- 926

DOCKET NUMBER 50-483
CALLAWAY PLANT, UNIT 1
LICENSE CONDITION 2.C.7.a - FIRE PROTECTION

Reference: ULNRC-814 dated May 7, 1984


The following information is provided relative to closing License Condition 2.C.7.a of the Callaway Operating License, NPF-25. This License Condition, relating to fire protection, resulted from a deferral requested by the referenced letter.

1. The South Penetration Room Halon system is considered complete and operational as a result of the testing and the addition of a sprinkler system for the electrical chase area. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. The SNUPPS Standard Plant FSAR was revised in Revision 15 to describe the added sprinkler system.
2. The line-type thermal detectors (Protecto-Wire) inside containment have been successfully tested and declared operable. Union Electric has determined that the thermal detectors for the cable trays on the control rod drive mechanism are not required and, therefore, has deleted them from the design. This has been reviewed by Region III Inspector, Mr. J. M. Ulie, and we understand his inspection report will close this item from the I&E perspective. This change does not necessitate an FSAR change.
3. The construction activities related to the Auxiliary and Control Building passive fire protection items described in the referenced letter were completed on August 24, 1984. As a result of modification implementation and closure of quality control paperwork, a small number of inoperable penetrations continue to exist. To ensure compliance with Technical Specifications and the Fire Protection Program until these are resolved, required fire watches are being maintained as compensatory measures.

Mr. Harold R. Denton
September 14, 1984
Page 2

We believe this submittal closes License Condition 2.C.7.a
of the Callaway Operating License.

Very truly yours,



for Donald F. Schnell

DS/msc


cc: J. Holonich

STATE OF MISSOURI)
) S S
CITY OF ST. LOUIS)

Robert J. Schukai, of lawful age, being first duly sworn upon oath says that he is General Manager-Engineering (Nuclear) for Union Electric Company; that he has read the foregoing document and knows the content thereof; that he has executed the same for and on behalf of said company with full power and authority to do so; and that the facts therein stated are true and correct to the best of his knowledge, information and belief.

By 
Robert J. Schukai
General Manager-Engineering
Nuclear

SUBSCRIBED and sworn to before me this 14th day of September, 1984


MARY C. GUINN
NOTARY PUBLIC—STATE OF MISSOURI
ST. LOUIS CITY
MY COMMISSION EXPIRES JUNE 16, 1986

cc: Gerald Charnoff, Esq.
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Nicholas A. Petrick
Executive Director
SNUPPS
5 Choke Cherry Road
Rockville, Maryland 20850

John H. Neisler
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

William Forney
Division of Projects and
Resident Programs, Chief, Section 1A
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Bruce Little
Callaway Resident Office
U.S. Nuclear Regulatory Commission
RR#1
Steedman, Missouri 65077

bcc: 3456-0021.6
Nuclear Date
DFS/Chrono
D. F. Schnell
J. F. McLaughlin
J. E. Birk
W. H. Weber
F. D. Field
R. J. Schukai
M. A. Stiller
S. E. Miltenberger
J. J. Beisman
Missouri Public Service Commission
D. W. Capone
A. C. Passwater
T. H. McFarland
R. P. Wendling
D. E. Shafer
D. J. Walker
G56.37 (CA-460)
Compliance (J. E. Davis)
3456-0033.1
3456-7860.1