


# LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

August 31, 1984

W3K84-2053  
Q-3-A35.07.60



Mr. John T. Collins  
Regional Administrator, Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

REFERENCE: LP&L letter W3K84-1884 dated August 13, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3  
Docket No. 50-382  
Significant Construction Deficiency No. 60  
"Turnover Documentation and Inadequate Hanger Weld Problems T&B"  
Eleventh Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on August 31, 1984.

At the present time, the evaluation of the walkdown results is scheduled to be completed in mid September 1984. The Final Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

*Sor* T. F. Gerrets  
Corporate Quality Assurance Manager

TFG:CNH:ESH

cc: Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8409210015 840831  
PDR ADDCK 05000382  
S PDR

*IE-27*  
*1/0*

Mr. John T. Collins

August 31, 1984

W3K84-2053

Page 2

cc: Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. E. L. Blake  
Shaw, Pittman, Potts & Trowbridge  
1800 M Street, N.W.  
Washington, D.C. 20036

Mr. W. M. Stevenson  
Monroe & Lemann  
1424 Whitney Building  
New Orleans, Louisiana 70130

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

Mr. W. A. Cross  
7910 Woodmont Avenue  
Suite 1200  
Bethesda, Maryland 20814