

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company
Turkey Point

Docket Nos. 50-250, 251
License Nos. DPR-31, 41

The following violation was identified during an inspection conducted between May 7 and June 9, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

Technical Specification (TS) 6.8.1 requires that written procedures and administrative policies shall be established, implemented and maintained that meet or exceed the requirements and recommendations of Section 5.1 and 5.3 of ANSI N18.7-1972 and Appendix "A" of USNRC Regulatory Guide 1.33.

Contrary to the above, on May 12, 1984, an Operating Procedure (OP) 1009.1, dated April 10, 1984, was found to be inadequately established and implemented in that an estimated critical condition, which was calculated in accordance with OP 1009.1, was in excess of 150 steps in error.

This is a Severity Level IV violation (Supplement I).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUL 13 1984