

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

34 SEP 10 P 1: 21 September 4, 1984

BLRD-50-438/84-27
BLRD-50-439/84-26

U.S. Nuclear Regulatory Commission
Region II
Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

BELLEFONTE NUCLEAR PLANT UNITS 1 AND 2 - DEFICIENCIES IN RECEIPT
INSPECTION BLRD-50-438/84-27, BLRD-50-439/84-26 - SECOND INTERIM REPORT


The subject deficiency was initially reported to NRC-OIE Inspector P. E. Fredrickson on March 28, 1984 in accordance with 10 CFR 50.55(e) as NCR 2975. A similar deficiency was later documented and reported to inspector D. M. Verrelli on April 17, 1984 as NCR 3063. This was followed by our interim report dated April 25, 1984. Below is our second interim report on both NCRs. We expect to submit our next report on or about March 12, 1985.

TVA is still reviewing receiving inspection checklists (RICs) as noted in our first report on this deficiency. Additional information will be provided upon completion of this review.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8409240044 840904
PDR ADDCK 05000438
S PDR

OFFICIAL COPY

TE 27 1/0