

APPENDIX A

NOTICE OF VIOLATION

Public Service Electric and
Gas Company
Salem Unit 2

Docket/License: 50-311/DPR-75

As a result of the inspection conducted on July 7, 1984 - August 13, 1984 and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984 (47 FR 8583), the following violation was identified:

- A. Unit 2 Technical Specification 6.8.1 and Regulatory Guide 1.33, Revision 2, require that procedures for startup, operation and shutdown of emergency core cooling systems and general procedures for cold shutdown to hot standby be implemented.
- i. Operating Procedure (OP) II-4.3.1, Safety Injection System-Normal Operation, requires that check off sheet 1, Safeguards Equipment Cabinet Lineup, be completed.
 - ii. Integrated Operating Procedure (IOP-2) dated August 6, 1984, Cold Shutdown to Hot Standby requires as a prerequisite, verification that the Safety Injection System be aligned for operation in accordance with its operating procedure.

Contrary to the above, on August 10, 1984, the required procedures were not implemented, in that there was no completed OP II-4.3.1 check off sheet 1 on file, and an operator signed off the verification of the Safety Injection system required by IOP 2 without identifying and correcting this discrepancy.

This is a Severity Level IV violation (Supplement 1) applicable to DPR-75.

Pursuant to the provisions of 10 CFR 2.201, Public Service Electric and Gas Company is hereby required to submit to this office within 30 days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including for each violation: (1) the corrective steps which have been taken and the results achieved; (2) the corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

8409240121 840829
PDR ADOCK 05000272
Q PDR