

ENCLOSURE 1

NOTICE OF VIOLATION

Tennessee Valley Authority
Brown Ferry 1, 2 and 3

Docket Nos. 50-259, 50-260, 50-296
License Nos. DPR-33, DPR-52 and DPR-68

The following violations were identified during an inspection conducted on May 21-25, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 71.5(a) requires that each licensee who delivers licensed material to a carrier for transport shall comply with the applicable requirements of the regulations appropriate to the mode of transport of DOT in 49 CFR Parts 170 through 189.

49 CFR 173.425(b)(6) requires that packaged radioactive material shipments must be braced so as to prevent shifting of lading under conditions normally incident to transportation.

Contrary to the above, a box of low specific activity radioactive waste shipped under control number BSMP 84-20 on April 4, 1984, was discovered to have shifted during transport upon arriving at the destination on April 10, 1984.

This is a Severity Level IV violation (Supplement V).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUN 28 1984

8409240306 840822
PDR ADDCK 05000259
Q PDR