

6200 Ook Tree Boulevard Independence OH 216-447-3153 Fax 216-447-3123 Mail Address: P.O. Box 94661 Cleveland, OH 44101-4661 Donald C. Shelton Senior Vice President Nuclear

October 02, 1995 PY-CEI/NRR-1986L

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Perry Nuclear Power Plant Docket No. 50-440 LER 95-005, LER 95-006, and LER 95-007

Gentlemen:

Enclosed are Licensee Event Reports 95-005, Inverter Failure Results in Reactor Scram; 95-006, Engineered Safety Feature (ESF) Actuation during Inverter Restoration; and 95-007, Improper Feedwater Pump Transfer Results in Reactor Scram.

If you have questions or require additional information, please contact Mr. James D. Kloosterman, Manager - Regulatory Affairs at (216) 280-5833.

Very truly yours,

GSC:sc

Enclosures: LER 95-005

LER 95-006

LER 95-007

cc: NRC Project Manager

NRC Resident Inspector Office

NRC Region III

050004

TESS.