



PECO ENERGY

Robert W. Boyce  
Plant Manager  
Limerick Generating Station

PECO Energy Company  
Limerick Generating Station  
PO Box 2300  
Sanatoga, PA 19464-0920  
215 327 1200 Ext. 2000

10CFR50.73

October 2, 1995  
Docket Nos. 50-352  
50-353  
License Nos. NPF-39  
NPF-85

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

SUBJECT: Licensee Event Report  
Limerick Generating Station - Unit 1 and Unit 2

This LER reports a condition prohibited by the Technical Specifications in that the Unit 1 'A' and 'B' and the Unit 2 'A' Primary Containment Post-LOCA Hydrogen Recombiners were inoperable due to a common cause. The cause was personnel error resulting in the inadequate development of a temperature recorder Post Modification Test.

|                  |  |
|------------------|--|
| Reference:       | Docket Nos.50-352<br>50-353  |
| Report Number:   | 1-95-007   |
| Revision Number: | 00   |
| Event Date:      | September 2, 1995  |
| Report Date:     | October 2, 1995  |
| Facility:        | Limerick Generating Station<br>P.O. Box 2300, Sanatoga, PA<br>19464-2300 |

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B), (a)(2)(v)(D), and (a)(2)(vii).

Very truly yours,

DMS:cah

cc: T. T. Martin, Administrator Region I, USNRC  
N. S. Perry, USNRC Senior Resident Inspector, LGS

000006

9510060011 951002  
PDR ADDCK 05000352  
S PDR