## APPENDIX A

## NOTICE OF VIOLATION

Pennsylvania Power and Light Company Susquehanna Steam Electric Station, Units 1 and 2 50-387 Docket Nos. 50-388 NPF-14 NPF-22

As a result of an inspection conducted on June 27, 1984, by a representative of the State of Washington Department of Social and Health Services of a shipment of radioactive waste sent from your facility in Berwick, Pennsylvania, on June 22, 1984, and in accordance with the NRC Enforcement Policy, 10 CFR 2, Appendix C, published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

10 CFR 71.5 prohibits delivery of licensed material to a carrier for transport unless the licensee complies with applicable regulations of the Department of Transportation in 49 CFR Parts 170-189.
49 CFR 173.425(b)(6) requires that packaged shipments of low specific activity material must be braced so as to prevent the shift of lading under conditions normally incident to transportation.

Contrary to the above, on June 27, 1984, licensed material, containing 1413.863 millicuries, identified as low specific activity, was delivered to a carrier for transport. Upon arrival at the burial facility in Richland, Washington, the shipment was found not to be braced so as to prevent the shift of lading under conditions normally incident to transportation.

This is a Severity Level V violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, the Pennsylvania Power and Light Company is hereby required to submit to this office within thirty days of the date of the letter transmitting this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.