




LOUISIANA

POWER & LIGHT/Waterford 3 SES/P. O. Box B/Killona, LA 70066

September 5, 1984

W3K84-2105
Q-3-A35.07.37
Q-3-A35.07.80
Q-3-A35.07.93

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiencies Nos. 37, 80, and 93
Extension Request
Interim Report

Due to the delay in the schedule for the accomplishment of Post Core Hot Functional Testing, the Final Reports for Significant Construction Deficiency Nos. 37, 80, and 93 are scheduled to be submitted to the USNRC on December 15, 1984.

Very truly yours,

T. F. Gerrets
Corporate Quality Assurance Manager

TFG:CNH:VBR

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE-27
1/0

8409260572 840905
PDR ADOCK 05000382
S PDR

Mr. John T. Collins
September 5, 1984
W3K84-2105
Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814