

315/89-08

316/89-08

MAR 23 1989

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Mr. I. T. Yin of this office on February 6-11, and 28, 1989, of activities at D. C. Cook, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. G. Smith, Jr., and others of your staff at the conclusion of the inspection. This also refers to the meeting on March 7, 1989, in the Region III office regarding your inspection efforts involving the auxiliary feedwater system at the D. C. Cook Nuclear Power Station.

The enclosed copy of our inspection report documents our evaluation of your corrective actions conducted for the findings identified in your self-initiated engineering oriented functional inspection of the auxiliary feedwater system.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

ORIGINAL SIGNED BY MONTREY C. WRIGHT

9510100252 890323
PDR ADOCK 05000315
G PDR

G. C. Wright, Chief
Operations Branch

Enclosure: Inspection Reports
No. 50-315/89008(DRS);
No. 50-316/89008(DRS)

See Attached Distribution

Yeo
RIII *Yin*
Yin/ib
3/21

RIII *Phillips*
Phillips

RIII *Burgess*
Burgess
3/21

RIII *Wright*
Wright
7/23

H005
1/1

MAR 23 1989

Indiana Michigan Power
Company

3

Distribution

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health