APR 0 6 1989

Docket No. 50-456 Docket No. 50-457

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the reactive safeguards inspection conducted by Ms. G. M. Christoffer and Mr. J. L. Belanger of this office between February 2 and March 28, 1989 of activities at Braidwood Nuclear Power Station, Units 1 and 2, authorized by Operating Licenses No. NPF-72 and No. NPF-77 and to the discussion of our findings with Mr. R. Querio and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

9510100277 890406 PDR ADOCK 05000456 Q PDR

L. Robert Greger, Chief Reactor Programs Branch

Enclosure: Inspection Reports No. 50-456/89010(DRSS); No. 50-457/89010(DRSS)

See Attached Distribution

Belanger/jaw

RIII Y JANK 189

Christoffer

RIII

RIII

July Hoos

100074

Distribution

cc w/enclosure: T. J. Maiman, Vice President, PWR Operations P. Kovack, Nuclear Licensing Manager S. Hunsader, Nuclear Licensing Administrator R. E. Querio, Station Manager P. L. Barnes, Regulatory Assurance Supervisor DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Braidwood Resident Inspector, RIII Byron D. W. Cassel, Jr., Esq. Richard Hubbard J. W. McCaffrey, Chief, Public Utilities Division H. S. Taylor, Quality Assurance Division E. Chan, OGC G. Berry, OGC Stephen P. Sands, NRR