


POST OFFICE BOX 2951 . BEAUMONT, TEXAS 77704 AREA CODE 713 838-6631

> September 12, 1984 RBG-18891 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-236



An interim or final status report concerning the piston wrist pins in the Standby Diesel Generator supplied by Transamerica Delaval, Incorporated will be provided by November 28, 1984.

Sincerely,

J. E. Booker

Manager-Engineering,

Nuclear Fuels & Licensing River Bend Nuclear Group

L. a. England for

JEB/PJD/1p

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

NRC Resident Inspector-Site

8409270447 840912