

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report No. 50-482/92-10

Operating License No. NPF-42

Licensee: Wolf Creek Nuclear Operating Corporation (WCNOC)
P.O. Box 411
Burlington, Kansas 66839

Facility Name: Wolf Creek Generating Station (WCGS)

Inspection At: WCGS, Burlington, Kansas

Inspection Conducted: May 4-8, 1992

Inspectors: T. W. Dexter, Senior Physical Security Specialist
A. B. Earnest, Physical Security Specialist

Approved:

Blaine Murray
Blaine Murray, Chief, Facilities Inspection
Programs Section

5/22/92
Date

Inspection Summary

Inspection Conducted May 4-8, 1992 (Report 50-482/92-10)

Areas Inspected: Routine, unannounced inspection of the physical security program. The areas inspected included: management support, security program plans and audits; protected and vital area barriers and isolation zones; protected area access control of personnel, packages, and vehicles; alarm station and communications; testing, maintenance, and compensatory measures; security training and qualification; security locks, keys and combinations; records, and reports.

Results: Within the areas inspected, no violations or deviations were identified. One concern was identified involving vital area barriers which is

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

discussed in paragraph 3.2.b. The following is a summary of the inspection results:

- o The security program was well managed and received very good management support.
- o Security organization personnel were motivated, well managed, and appeared capable of performing to licensee requirements.
- o The preventive maintenance program for security equipment was well implemented and a formal schedule was being followed.
- o The security training program was a well rounded program with very good documentation. Training aids were readily available and used effectively.
- o The firing range program was aggressive, and the various training aids and facilities at the range a great deal of self initiative by the security organization.
- o The security locks, keys, and combinations program was effective.
- o The required records and reports were all in order, a good analysis of events was being performed, and sound corrective actions were being implemented.
- o The security audit program was comprehensive and performance oriented.
- o A concern was identified regarding the number of unsecured vital area doors. Aggressive corrective actions had been implemented by the licensee concerning this matter prior to this inspection.

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.