

Appendix A

NOTICE OF VIOLATION

Niagara Mohawk Power Corporation
Nine Mile Point, Unit 1

Docket No. 50-220
License No. DPR-63

As a result of the inspection conducted on April 1-30 and May 1-31, 1984 and in accordance with the NRC Enforcement Policy, (10 CFR2, Appendix C), the following violation was identified:

Technical Specification 6.8.1 requires, in part, that written procedures and administrative policies shall be established, implemented and maintained.

Fuel Handling Procedure FHP-2A, "Reactor Building Clean Room Work and Tool Control", Revision 2, Section 7.D requires, in part, that all tools and consumable material used over the open reactor vessel be listed on an inventory checklist.

Contrary to the above, on April 11, 1984, one pair of binoculars was on the refueling bridge over the open reactor vessel and was not listed on the inventory checklist.

This is a Severity Level V violation (Supplement 1).

Although 10 CFR2 Section 2.201 requires you to submit to this office within 20 days of your receipt of this notice, a written statement of explanation, we note that this violation was corrected prior to the completion of our inspection, and therefore, no response with respect to this matter is required.

8409270823 840905
PDR ADOCK 05000220
Q PDR