

WATERFORD 3 SES . P.O. BOX B . KILLONA, LA 70066

September 14, 1984

W3P84-2547 Q-3-A35.07.108 3-A1.01.04

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76012

REFERENCE: LP&L Letter W3K84-2033 dated August 30, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Significant Construction Deficiency No. 108

"Potential Failure to Comply with FSAR Safe Shutdown Commitment"

Fifth Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on September 14, 1984.

At the present time, verification is ongoing and is scheduled to be completed by the end of September, 1984. The Final Report is scheduled to be submitted to the USNRC on September 28, 1984.

Very truly yours,

Nuclear Support & Licensing Manager

KWC/TJG/ss

cc: Director

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission

Washington, D.C. 20555

IE-27

Mr. John T. Collins W3P84-2547 Page 2

cc: Director
Office of Management
Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E.L. Blake Shaw, Pittman, Potts & Trowbridge 1800 M. Street, N.W. Washington, D.C. 20036

Mr. W.M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Mr. W.A. Cross 7910 Woodmont Avenue Suite 1200 Bethesda, Maryland 20814