



MIDDLE SOUTH
UTILITIES SYSTEM

LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
NEW ORLEANS, LOUISIANA


• P.O. BOX 8008
70174-8008

• (504) 388-2345

September 14, 1984

W3P84-2552
Q-3-A35.07.114
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



REFERENCE: LP&L letter W3K84-2055 dated August 31, 1984

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Significant Construction Deficiency No. 114
"Possible Damage to Safety Related Equipment Due to Water Hammers"
Third Interim Report

The above referenced letter indicated submittal of the Final Report to the USNRC on September 14, 1984.

At the present time, verification of the corrective action is scheduled to be completed in mid September, 1984. The Final Report is scheduled to be submitted to the USNRC on September 21, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/TJG/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

IE-27
1/0

8409270837 840914
PDR ADDCK 05000382
PDR

Mr. John T. Gollins
W3P84-2552
September 14, 1984
Page 2

cc: Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814