



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

August 27, 1984  
(NMP2L 0144)

Mr. R. W. Starostecki, Director  
U.S. Nuclear Regulatory Commission  
Region I  
Division of Project and Resident Programs  
631 Park Avenue  
King of Prussia, PA 19406

Re: Nine Mile Point Unit 2  
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report in accordance with 10CFR50.55(e) for the problem concerning welds in the control rod drive support system. This problem was reported via telecon to S. Collins of your staff on July 26, 1984.

Very truly yours,

C. V. Mangan  
Vice President  
Nuclear Engineering & Licensing

TL:ja  
Enclosure  
xc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Project File (2)

8410020039 840827  
PDR ADOCK 05000410  
S PDR

NIAGARA MOHAWK POWER CORPORATION  
NINE MILE POINT - UNIT 2  
DOCKET NO. 50-410

Interim Report for a Problem  
Concerning Welds in CRD Support System  
(55(e)-84-29)

Description of the Problem

The problem concerns welds in the control rod drive support system furnished by Reactor Controls, Incorporated (RCI). An inspection of 12 randomly selected welds indicated that four welds were 7/16 inch instead of the 1/2 inch shown on RCI drawings. The matter is still under investigation and a final report will be submitted by November 12, 1984.