



NIAGARA MOHAWK POWER CORPORATION / 300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202 / TELEPHONE (315) 474-1511

September 13, 1984
(NMP2L 0161)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

Re: Nine Mile Point - Unit 2
Docket No. 50-410

Dear Mr. Starostecki:

Enclosed is an interim report, in accordance with 10CFR50.55(e), for the problem concerning the reactor core isolation cooling turbine steam admission line. This problem was reported via tel-con from G. Griffith (Niagara Mohawk Licensing) to P. Russ of your staff on August 15, 1984.

Very truly yours,

C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG/pbd

xc: Director of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector

Project File (2)

B410020045 B40913
PDR ADDCK 05000410
S PDR

IE27

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem
Concerning Reactor Core Isolation Cooling System
Turbine Steam Admission Line
(55(e)-84-33)

Description of the Problem

The steam supply line to the reactor core isolation cooling system turbine contains a vertical section which could permit accumulation of condensate. This column of condensate may be carried into the turbine on system start.

The matter is still under investigation and a final report will be submitted by December 6, 1984.