

APPENDIX A

NOTICE OF VIOLATION

Niagara Mohawk Power Corporation
Nine Mile Point, Unit 1

Docket No. 50-220
License No. DPR-63

As a result of the inspection conducted on June 1 - July 16, 1984 and in accordance with the revised NRC Enforcement Policy (10 CFR 2, Appendix C) published in the Federal Register on March 8, 1984 (49 FR 8583), the following violation was identified:

Technical Specification 6.8.1 requires, in part, that written procedures shall be established that meet or exceed the requirements of Regulatory Guide 1.33.

Regulatory Guide 1.33 requires that written procedures be established for maintaining primary containment integrity.

Contrary to the above, on July 10, 1984, the licensee had failed to establish written procedures to ensure that the outside containment isolation valves for breathing air and service water to the drywell are closed. These valves are required to be closed to maintain primary containment integrity.

This is a Severity Level IV violation (Supplement I).

Although 10 CFR 2, Section 2.201, requires you to submit to this office, within thirty days of the date of the letter which transmitted this Notice, a written statement of explanation, we note that this violation was corrected prior to the completion of our inspection, and therefore, no response with respect to this matter is required.

8410020405 840907
PDR ADOCK 05000220
G PDR

OFFICIAL RECORD COPY