

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Joseph M. Farley - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 6 4	PAGE (3) 1 OF 0 1
--	--------------------------------------	----------------------

TITLE (4)  
Steam Generator Tube Plugging

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)													
0	9	0	8	8	4	8	4	0	0	0	9	0	0	9	2	4	8	4		0	5	0	0	0

OPERATING MODE (9) 5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)				
POWER LEVEL (10) 0	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input type="checkbox"/> 60.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)	
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 60.36(a)(1)	<input type="checkbox"/> 60.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)	
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 60.36(a)(2)	<input type="checkbox"/> 60.73(a)(2)(vii)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)	
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 60.73(a)(2)(i)	<input type="checkbox"/> 60.73(a)(2)(viii)(A)		
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 60.73(a)(2)(ii)	<input type="checkbox"/> 60.73(a)(2)(viii)(B)		
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 60.73(a)(2)(iii)	<input type="checkbox"/> 60.73(c)(2)(x)		

LICENSEE CONTACT FOR THIS LER (12)

NAME J. D. Woodard	TELEPHONE NUMBER AREA CODE: 2 0 5 8 9 9 - 5 1 5 6
-----------------------	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH DAY YEAR
--	--	-------------------------------	----------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

In accordance with Technical Specification 4.4.6.5.a, the following tube plugging report is submitted.

During re-analysis of the Unit 2 Cycle II-III refueling outage inservice eddy current test data, two tubes were identified in the 2B steam generator with tube wall degradation exceeding the pluggable limit. The unit was shut down on 8-31-84 and these two tubes were plugged. Additionally, one tube in the 2A steam generator which was identified by leak testing was plugged. Tube plugging was completed 9-8-84.

8410050463 840924  
PDR ADOCK 05000364  
S PDR

IEZZ  
X

**Mailing Address**

Alabama Power Company  
600 North 18th Street  
Post Office Box 2641  
Birmingham, Alabama 35291  
Telephone 205 787-6090

**R. P. McDonald**  
Senior Vice President  
Fintridge Building



Alabama Power  
the southern electric system

September 24, 1984

Docket No. 364


Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Sir:

Joseph M. Farley Nuclear Plant, Unit 2, Licensee Event Report  
No. LER 84-009-00 is forwarded in accordance with Technical Specification  
4.4.6.5.a.

If you have any questions, please advise.

Yours very truly,

  
R. P. McDonald

RPM/DSM:sam

Enclosure

xc: IE, Region II

IE22  
1/1