



Georgia Power

the southern electric system

Edwin I. Hatch Nuclear Plant

February 14, 1979
PM-79-162

PLANT E. I. HATCH
Licensee Event Report
Docket No. 50-321


United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

ATTENTION: Mr. James P. O'Reilly

Pursuant to Section 6.9.1.2.b (2) of Hatch Unit 1 Technical Specifications,
please find attached Reportable Occurrence Report No. 50-321/1979-07.

Please be advised that this report was erroneously submitted as Report No.
50-321/1979-22, which was an incorrect number. Reportable Occurrence Report
No. 50-321/1979-22, dated 2-9-79, should be discarded and replaced with
Reportable Occurrence Report No. 50-321/1979-07.

The valve number was given as E51-F006 in the original report, but should
have been E51-F019.


M. Manry
Plant Manager

RTN:jc

xc: W. A. Widner
R. D. Baker
Control Room
File

7902230099

A002
5/11

5