

SALEM FIRE PROTECTION PROGRAM
NRC QUESTION 3.a(2) - SILICON FOAM SEALS
ADDITIONAL INFORMATION

As requested by the NRC in our meeting at Salem on January 31 and February 1, 1979, the following test reports are submitted for the silicon foam seals.

Unit #1 .Requirement - 1½ hour barrier.

.Factory Mutual test report 24963 dated August 5, 1975.

.Dow Corning letter of February 25, 1976.

.SEMCO test report dated June 28, 1976.

.BISCO test report dated June 14, 1976.

.Fog nozzles used at Salem are Wilson Cousins
Model HN4L - 1½ - Electrical Fog Nozzle.

Unit #2 .Factory Mutual Research Test Report Serial No. OAOQ3.AM
dated May 18, 1977.

WG:hh
2/7/79

7902230198

DOOR SCHEDULE
SALEM FIRE PROTECTION PROGRAM
QUESTION 3a(1)

Attached are PSE&G drawings No. 207095 A-8798-20 and 236894 A1464-4, showing the door schedules for Salem Units 1 and 2. Changes being made to conform with fire protection program requirements are marked in red.

WG:hh
2/7/79