

933 EAST PIERCE

COUNCIL BLUFFS, IOWA 51501 . PHONE 322-0231

DEPARTMENT OF RADIOLOGY

Section of Diagnostic Imaging Section of Nuclear Medicine Section of Radiation Medicine and Oncology

January 19,1980

Francis A. St. Mary License Management Branch Division of Fuel Cycle and Material Safety United States Nuclear Regulatory Commission Washington, D.C. 20555

License No. 14-0 0950-03 Control No. 98809

Gentlemen

Mr. Myron Goede, Radiation Physicist, has indicated that our teletherapy unit may be brought into compliance with the provisions of Section 20. 105 (a) of 10 CFR part 20, by applying option 2, stated in your letter, dated July 23, 1979.

Accordingly, a record shall be kept daily, in the daily log, indicating those instances in which the beamstopper was not interposed in the path of the primary beam. It is anticipated that the average radiation level outside of the room will be 0, since the beam will be pointed at the primary wall only if the beamstopper is not interposed to intercept the primary beam. The occupancy times are likely to be less than one fourth hour per hour and 10 hours per week.

20 111 Star Will 102 550

CREAK SHERE

COPIES SENT TO OFF. OF

INSPECTION AND ENDOY

Sincerely

(8192130531] 1p.

Chairman, Radiation Safety Committee