IC Form 34 83)	-			LICE	INSEE EVE	T REP	ORT (I	LER)	AP	PIRES: 8/31/	NO. 3		
									CKET NUMBER	2)	L	PAGE	135
Monticello Nuclear Generating Plant 0 15 10							15 10 101	01216	B	1 OF	012		
TLE (4)	-												
			T Actuated	By Top	ALEPORT DAT	al Mor	litor	OTHER F	ACILITIES INVOL	VED (SI			
EVENT DATE ISI LER NUMBER (6) MONTH DAY YEAR YEAR SEQUENTIAL NUMBER							FACILITY NAM		DOCANT NU	MBERI	S)		
ONTH	UAT	EAR TEAM	NUMBER	NUMBER						0 5 0	101	011	1
.		1.1.1.			1/1 0/8	8 4				0 1510	10	0, 1	
1 015	8 9 0	4 8 4	ORT IS SUBMITTED	PURSUANT			CFR §: (C	heck one or more a	t the following) (1)	And in case of the survey of t			
	ATING		402(6'		20.406(a)		X	50.73(a)(2)(iv)		73,71			
POWER 20.408(a)(1)(0) LEVEL 01010 20.408(a)(1)(8)			50.36(e)(1) 50.36(e)(2) 50.73(e)(2)(i)			50.73(e)(2)(v)		73.71(c) OTHER (Specify in Abstract			tract		
						50.73(a)(2) -1) 50.73(a)(2)(viii)(A		Delow and in Text, NRC 366A)		Form			
			405(a)(1)(iii) 405(a)(1)(iv)	H	80.73(a)(2)(ii)		H	50.73(s)(2)(viii)(8		1.1			
			.406(a)(1)(v)		50.73(a)(2)(iii)			50 73(a)(2)(x)					
					LICENSEE CONTAC	FOR THIS	LER (12)			TELEPHONE	NUME	ER	
SMAN									AREA CODE	1			
M	ichae	1 F. Ham	ner, I & C	Engine	er				61112	21915	1-	5 11	151
			COMPLETE	ONE LINE FOR	R EACH COMPONEN	T FAILURE	DESCRIBE	O IN THIS REPOR	IT (13)		-		
CAUSE	SYSTEM	COMPONENT	MANUFAC. TURER	REPORTABLE TO NPROS	E	CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTA TO NPR		*	
				-					1				
		111							111			Law	Tues
			SUPPLEM	ENTAL REPOR	T EXPECTED (14)				EXPEC'	TED -	NONTH	DAY	YEA
YES (If you, complete EXPECTED SUBMISSION DATE) X NO								DATE (15)		1		1	
	the a in sp schee	unmonia a purious t iuled. 7	m (Contro und hydrog trips of t The replac on the day	en chlo he moni ement s	tors. Th chedule h	tors t e cass	ape c ettes	had not	been rep	laced	as		
		84111 PDR 4 5	90191 84 DOCK 050	41108 000263 PDR							Ŧ	111	

.

1

reference and the form

NRC Form 386A (9-83) LICENSEE F	EVENT REPORT (LER) TEXT CONTIN	UATION	U.S. NUCLEAR REGULATORY COMMISSION A/PROVED OMB NO. 3150-0104 EXPIRES: 8/31/85				
FACILITY NAME (1)	GOCKET NUMBER (2)	LER NU	MBEH (6)	PAGE (3)			
			UNBER REVISION				
Monticello	0 15 10 10 10 12 1613	814 -01	$ _{3 _{0}} - _{0 _{0}}$	0 12 OF 0 12			
TEXT IN more space is required, use additional NRC Form 365A	('a) (17)						

During cold shutdown on October 9, 1984 at approximately 1800, the EFT System (Control Room HVAC system) (System Code VI) automatically transferred to the toxic chemical emergency mode (isolation of outside air intake and exhaust) when hydrogen chloride monitor AT-9036 (MDA Scientific Model 7025 FAN) (Componet Code AA) cassette paper tape supply was exhaused, resulting in a spurious trip of the monitor. Subsequently, at approximately 1936, the system again transferred to the emergency mode when ammonia monitor AT-9031 (MDA Scientific Model 7060 FAN) cassette paper tape supply was exhausted, also resulting in a spurious trip of the monitor. New cassettes were installed on all toxic chemical monitors and the EFT system returned to normal operation.

Cause of this event was failure of the assigned NSP technician to replace the cassettes as scheduled on October 9, 1984 (a cognitive error). The cassettes must be replaced weekly with a maximum deviation of approximately 8 hours. Replacement is controlled by approved procedure and the surveillance scheduling program. Involvement of the responsible technician in a highpriority outage task on the day of the event contributed to the occurrence. Work location conditions did not contribute to the event. The replacement schedule has been revised to provide for replacement at the beginning of the scheduled day which will limit the distraction caused by other work activities.

There was no effect on public health and safety because the safety function of the ErT system was initiated.

There has been one previous similar occurrence, LER 84-017.



Northern States Power Company

414 Nicollet Mail Minneapolis, Minnesota 55401 Telephone (612) 330-5500



November 8, 1984

U S Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

> MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

E-Mode of EFT Actuated BY Toxic Chemical Monitors

The License Event Report for this occurrence is attached.

This event was reported via Emergency Notification System per '9 CFR Part /2 on October 9, 1984.

Thoreca Vik

David Musolf Manager - Nuclear Support Services

DMM/MMV/dab

c: Regional Adminiscrator-III, NRC NRR Project Manager, NRC Resident Inspector, NRC MPCA Attn: J W Ferman

Attachment

1E22