

**CP&L**

Carolina Power & Light Company

*Docket file*  
OFFICIAL COPY

~~84 OCT 5~~ 3400263 A7:56

Brunswick Steam Electric Plant  
P. O. Box 10429  
Southport, NC 28461-0429

October 1, 1984

FILE: B09-13510C  
SERIAL: BSEP/84-2061

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Suite 2900  
101 Marietta Street, NW  
Atlanta, GA 30323

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1  
DOCKET NO. 50-325  
LICENSE NO. DPR-71  
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8 AND  
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-84-3)

Dear Mr. O'Reilly:

During Unit 1 power operation concurrent with an ongoing Unit 2 refueling/maintenance outage, two Unit 1 fire barrier LCOs were respectively initiated on August 27, 1984, to permit the repair of fire door Nos. 111 and 201. Door No. 111, located on the 23-foot elevation of the common Unit 1/ Unit 2 Control Building, provides personnel access to the Unit 1 cable spread vault. A problem with the door closing mechanism prevented automatic closure. Door No. 201, located on the 37-foot elevation of the common Unit 1/Unit 2 Augmented Off-Gas Building, provides personnel access to the building. Problems with the door latches prevented it from opening. Required repairs to fire door Nos. 111 and 201 were completed, and the doors were respectively returned to service on September 4 and 6, 1984. During the time period the subject LCOs were in effect, appropriate fire watches were maintained.

Very truly yours,

*C. R. Dietz*

C. R. Dietz, General Manager  
Brunswick Steam Electric Plant

MJP/smp/LETPS1

Enclosure

cc: Mr. R. C. DeYoung  
NRC Document Control Desk

8411190333 841001  
PDR ADOCK 05000325  
S PDR

1/0  
*Te 22*